

K-tully -

10-5-76 - Talked to Mr. Dickensen on telephone; said he would be plugging well in a month or so - (K.O.) Original owner (Dave Wells) has passed away

With Sample #1  
097 - 30101  
Sec 6

drilled to 1135' & plan on going deeper - (Nov '72) Last rpt. only dr.

FILE NOTATIONS

Entered in MWD File	..... ✓	Checked by Chief	.....
Location Map Firmed	..... ✓	Approval Letter	11-21-72
Card Indexed	..... ✓	Disapproval Letter	.....

COMPLETION DATA:

Date Well Completed	.....	Location Inspected	.....
DW..... RW..... TA.....		Bond released	
GW..... OS..... PA.....		State or Fee Land	.....

LOGS FILED

Driller's Log.....  
 Electric logs (No.) .....  
 R..... I..... Dual I Log..... CR-N..... Micro.....  
 BHC Sonic CR..... Lat..... HI-L..... Sonic.....  
 CBLog..... CCLog..... Others.....

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL & GAS

Nekwyn A. Nordeen110330  
5. Lease Designation and Serial No.

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work

DRILL  DEEPEN  PLUG BACK

b. Type of Well

Oil Well  Gas Well  Other  Single Zone  Multiple Zone

2. Name of Operator

Schurr-Dickinson-Gregg Oil Co.

P.O. Box #5 Mexican Hat, Utah 84531

4. Location of Well (Report location clearly and in accordance with any State requirements.\*)

At surface  
1844 Ft. from South line and 839 Ft. from West line of  
Sec. 6-Township 42 South, Range 19 East.S.L.M. Existing well  
At proposed prod. zone  
Same

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

8. Farm or Lease Name

Utah Southern #1

9. Well No. Mexican Hat Deepen  
Wildcat Pool Wildcat

10. Field and Pool, or Wildcat

76-42S-19E-Salt Lake

11. Sec., T., R., M., or Blk. and Survey or Area

14. Distance in miles and direction from nearest town or post office\*

12. County or Parrish 13. State

San Juan Utah

15. Distance from proposed\* location to nearest property or lease line, ft. (Also to nearest drlg. line, if any)

16. No. of acres in lease

17. No. of acres assigned to this well

18. Distance from proposed location\* to nearest well, drilling, completed, or applied for, on this lease, ft.

19. Proposed depth

20. Rotary or cable tools

21. Elevations (Show whether DF, RT, GR, etc.)

22. Approx. date work will start\*

4,275 Above sea level

November 11th

23.

PROPOSED CASING AND CEMENTING PROGRAM

Size of Hole	Size of Casing	Weight per Foot	Setting Depth	Quantity of Cement
<u>6 inches</u>	<u>4 inch I.D.</u>		<u>1,500 Ft.</u>	<u>20 Bags</u>

We are deepening an existing well, the present well has about 200 ft., of 6 inch Surface casing cemented in. We will drill to about 1,500 feet, put in a 4 inch casing if we get any production, and cement it in. We are going to use a blow out preventer. This well was producing about 2 barrells of oil a day from a depth of 300 foot. We think we will hit pay at around 1,300 foot.

*SEWWSal*

*Re-entry  
Hoffel*

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: If proposal is to deepen or plug back, give data on present productive zone and proposed new productive zone. If proposal is to drill or deepen directionally, give pertinent data on subsurface locations and measured and true vertical depths. Give blowout preventer program, if any.

24.

Signed [Signature] Title President Date Nov. 9, 1972

(This space for Federal or State office use)

Permit No. 43-037-30101 Approval Date

Approved by..... Title..... Date.....


Conditions of approval, if any:

*10-5-76 Talked to Mr Dickinson on telephone. Said he would be plugging well in a month or so - KO Original owner (Dave Wells) has passed away.*

SCHURR, DICKINSON AND GREGG OIL COMPANY  
box 5  
MEXICAN HAT, UTAH

WELL LOCATION

1844 ft. from the South line and 839 ft.  
from the West line of section 6 T. 42 S.,  
R. 19 E. S. L. M.



SURVEYOR'S CERTIFICATE


I, Donald V. Blake, a registered professional land surveyor licensed to practice in the State of Utah do solemnly swear that the map shown hereon was prepared from the notes of an actual field survey performed by me and under authority on the 7th day of November, 1972 and that all lines and dimensions shown thereon are true and correct to the best of my knowledge and belief.

*Donald V. Blake*  
Reg. Land Surveyor license No. 2759

SCHURR, DICKINSON AND GREGG OIL COMPANY  
Box 5  
MEXICAN HAT, UTAH

WELL LOCATION

3075 ft. from the North line and 576 ft.  
from the East line of Section 7, T. 42 S.,  
R. 19 E., S. L. M.



SURVEYOR'S CERTIFICATE

I, Donald V. Blake, a registered professional land surveyor or licensed to practice in the State of Utah do solemnly swear that the map shown hereon was prepared from the notes of an actual field survey performed by me and under authority on the 7th day of November, 1972 and that all lines and dimensions shown thereon are true and correct to the best of my knowledge and belief.

*Donald V. Blake*  
Reg. Land Surveyor license No. 2759

Nov. 16, 1972

Lions;

Our sending the description on the plot  
that we're drilling the well on.

NEKESE

11/21/72  
Dickinson called  
& stated that was  
re-entry of existing  
well  
S.A.

November 21, 1972

Mr. G.R. Dickinson  
Box 5  
Mexican Hat, Utah

Re: Well No. Utah #1  
Sec. 7, T. 42 S, R. 19 E,  
San Juan County, Utah

Dear Jerry:

We are in receipt of your surveyor's plat of November 16, 1972, however, we are unable to determine if this is a new well or the re-entry of one of the seven old wells located in Section 7, please advise.

If said plat refers to a new well, approval will be conditional upon the following:

- (a) written notification as to why the well is located outside of the 500' limitation set forth under Rule C-3, page 30. (see enclosed)
- (b) a minimum of 3 joints of surface casing being set and cemented from top to bottom.
- (c) written notification as to the type, and subsequent testing procedures, of the blowout prevention equipment to be installed on said well.

Should you have any questions, please do not hesitate to contact this office.

Very truly yours,

DIVISION OF OIL & GAS CONSERVATION

CLEON B. FEIGHT  
DIRECTOR

CBF:sd

November 18, 1971

Schurr-Dickinson-Cregg  
P.O. Box 5  
Mexican Hat, Utah

ATTENTION: G.R. Dickinson

Re: Well No's:  
Utah #1,  
Sec. 7, T. 42 S, R. 19 E,  
Nelwyn Nordeen #3,  
Sec. 5, T. 42 S, R. 19 E,  
San Juan County, Utah

Dear Mr. Dickinson:

This letter is to advise you that the "Well Completion or Recompletion Report and Log" and electric and/or radioactivity logs for the above referred to wells are due and have not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3, in duplicate, and forward them to this office as soon as possible. If electric and/or radioactivity logs were not run, please make a statement to this effect in order to keep our records accurate and complete.

Your prompt attention to the above will be greatly appreciated.

Very truly yours,

DIVISION OF OIL & GAS CONSERVATION

SCHERRE WILCOX  
EXECUTIVE SECRETARY

SW



CALVIN L. RAMPTON  
*Governor*

GORDON E. HARMSTON  
*Executive Director,*  
NATURAL RESOURCES

CLEON B. FEIGHT  
*Director*

OIL, GAS, AND MINING BOARD

GUY N. CARDON  
*Chairman*

CHARLES R. HENDERSON  
ROBERT R. NORMAN  
JAMES P. COWLEY  
HYRUM L. LEE

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

January 29, 1976

Schurr-Dickenson-Gregg  
P. O. Box #5  
Mexican Hat, Utah 84531

Re: Well No. Nelwyn Nordeen #3  
Sec. 5, T. 42S, R. 19E  
San Juan County, Utah  
Well No. Utah #1  
Sec. 7, T. 42S, R. 19E  
San Juan County, Utah

Gentleman:

This letter is to advise you that the "Well Completion or Recompletion Report and Log" and electric and or radioactivity logs for the above referred to well are due and have not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3 in duplicate, and forward them to this office as possible. If electric and or radioactivity logs were not run, please make a statement to this effect in order that we may keep our records accurate and complete.

Your prompt attention to the above will be greatly appreciated.

Very truly yours,

DIVISION OF OIL, GAS, AND MINING

KATHY OSTLER  
RECORDS CLERK



CALVIN L. RAMPTON  
Governor

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

CLEON B. FEIGHT  
Director

OIL, GAS, AND MINING BOARD

GUY N. CARDON  
Chairman

CHARLES R. HENDERSON  
ROBERT R. NORMAN  
JAMES P. COWLEY  
HYRUM L. LEE

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771  
September 22, 1976

Gerald R. Dickenson  
909 Livesay Drive  
Cortez, Colorado 81321

Re: Well No. Nelwyn Nordeen #3  
Sec. 5, T. 42S, R. 19E  
San Juan County, Utah  
Well No. Etah #1  
Sec. 7, T. 42S, R. 19E  
San Juan County, Utah  
SECOND REQUEST

refer to  
memo  
11-18-74

Gentleman:

This letter is to advise you that the Well Completion or Recompletion Report and Log for the above referred to well is due and has not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3 in duplicate, and forward them to this office as soon as possible.

Thank you for your cooperation relative to the above.

Very truly yours,

DIVISION OF OIL, GAS, AND MINING

KATHY OSTLER  
RECORDS CLERK



SCOTT M. MATHESON  
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

I. DANIEL STEWART  
Chairman

CLEON B. FEIGHT  
Director

CHARLES R. HENDERSON  
JOHN L. BELL  
THADIS W. BOX  
C. RAY JUVELIN

August 10, 1978

Gerald R. Dickinson  
909 Livesay Drive  
Cortez, Colorado 81321

Re: Well No. Nelwyn Nordeen #3  
Sec. 5, T. 42S, R. 19E  
San Juan County, Utah

Well No. Utah #1  
Sec. 7, T. 42S, R. 19E  
San Juan County, Utah

Gentlemen:

This letter is to advise you that the Well Completion or Recompletion Report and Log for the above referred to well is due and has not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3, in duplicate, and forward them to this office as soon as possible.

Thank you for your cooperation relative to the above.

Very truly yours,

DIVISION OF OIL, GAS, & MINING

Tammy Edge  
Typist



SCOTT M. MATHESON  
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

I. DANIEL STEWART  
Chairman

CHARLES R. HENDERSON  
JOHN L. BELL  
THADIS W. BOX  
C. RAY JUVELIN

CLEON B. FEIGHT  
Director

August 10, 1978

Gerald R. Dickinson  
909 Livesay Drive  
Cortez, Colorado 81321



Re: Well No. Nelwyn Nordeen #3  
Sec. 5, T. 42S, R. 19E  
San Juan County, Utah

Well No. Utah #1  
Sec. 7, T. 42S, R. 19E  
San Juan County, Utah

Gentlemen:

This letter is to advise you that the Well Completion or Recompletion Report and Log for the above referred to well is due and has not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3, in duplicate, and forward them to this office as soon as possible.

Thank you for your cooperation relative to the above.

Very truly yours,

DIVISION OF OIL, GAS, & MINING

Tammy Edge  
Typist

*No reports under #5  
#2 Dick Cross  
Log of...*

*When Shiprock Corp took over as operator they changed Nordeen #3 to Nordeen #5. Would you see if the reports are filed under Nordeen #5.*

*They also changed Ellis A D & G Utah #1 to #2 Dickinson Crossing please check on this*

SCOTT M. MATHESON  
Governor



OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771  
January 3, 1979

I. DANIEL STEWART  
Chairman

CLEON B. FEIGHT  
Director

CHARLES R. HENDERSON  
JOHN L. BELL  
THADIS W. BOX  
C. RAY JUVELIN

Williams Ranches, Inc.  
Rt. 1 Box 52  
Blythe, California 92225

Re: Please see attached sheet for wells  
and locations-

Gentlemen:

This letter is to advise you that the Well Completion or Recompletion Report and Log for the above referred to wells are due and have not been filed with this office as required by our rules and regulations.

Please complete the enclosed Form OGC-3, in duplicate, and forward them to this office as soon as possible.

If you are not the present operator of all mentioned wells, please indicate so.

Thank you for your cooperation relative to the above.

Very truly yours,

DIVISION OF OIL, GAS, AND MINING

KATHY AVILA  
RECORDS CLERK

Attachment,  
List of wells requiring well Completion forms

- 1) Nordeen #6  
Sec. 5, T. 42S, R. 19E,  
San Juan County, Utah
- 2) Nordeen #7  
Sec. 5, T. 42S, R. 19E,  
San Juan County, Utah
- 3) Nordeen #1-A  
Sec. 6, T. 42S, R. 19E,  
San Juan County, Utah
- 4) Nelwyn Nordeen #3  
Sec. 5, T. 42S, R. 19E,  
San Juan County, Utah
- 5) Utah No. 1  
Sec. 7, T. 42S, R. 19E,  
San Juan County, Utah



SCOTT M. MATHESON  
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

I. DANIEL STEWART  
Chairman

CLEON B. FEIGHT  
Director

CHARLES R. HENDERSON  
JOHN L. BELL  
THADIS W. BOX  
C. RAY JUVELIN

February 2, 1979

Williams Ranches  
Route 1, Box 52  
Blythe, California 92225

Re: Well No. Nordeen #1-A  
Sec. 6, T. 42S, R. 19E,  
San Juan County, Utah

Well No. Nelwyn Nordeen 3  
Sec. 5, T. 42S, R. 19E,  
San Juan County, Utah

Well No. Utah No. 1  
Sec. 7, T. 42S, R. 19E,  
San Juan County, Utah

Gentlemen:

Please find enclosed the original application on the above referred to wells. We wrote Gerald Dickinson for these reports, but were advised by him that Shiprock took over these wells. We haven't received any correspondance from Shiprock, and would appreciate any reports available on these wells.

Thank you for your cooperation relative to the above.

Very truly yours,

DIVISION OF OIL, GAS, AND MINING

*Kathy Avila*

KATHY AVILA  
RECORDS CLERK

/enclosure

24

12  
24

# WILLIAMS RANCHES

## Jack Williams

ROUTE 1, BOX 52 • BLYTHE, CALIF.



Phone 922-2222 and 922-4422

ON THE COLORADO RIVER

CATTLE • CITRUS • ALFALFA • RUNNING HORSES •

24

February 20, 1979

Kathy Avila, Records Clerk  
Division of Oil, Gas and Mining  
1588 West North Temple  
Salt Lake City, UT 84116

Re: Well No. Nordeen #1-A  
Sec 6, T42s, R 19E

Well No. Nordeen #3  
Sec 5, T42S R19E

Well No. Utah No. 1  
Sec. 7, T42S R19E



In response to your letter February 2, I do not have any reports on the above wells. We took over operations from Shiprock in September 1977; but received no information on these wells.

If possible, we would like to drill these wells in the future. Is there a deadline as to when wells must be drilled. If not, should a monthly Sundry Notice and Report on Wells be filed on each of the above wells until time of drilling.

Sincerely yours,

*Jill Johnson*  
Jill Johnson



SCOTT M. MATHESON  
Governor

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

CLEON B. FEIGHT  
Director

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON  
Chairman

JOHN L. BELL  
C. RAY JUVELIN  
THADIS W. BOX  
CONSTANCE K. LUNDBERG  
EDWARD T. BECK  
E. STEELE McINTYRE

February 26, 1979

Williams Ranches  
Route 1, Box 52  
Blythe, California 92225

Re: Well No. Nordeen #1-A  
Sec. 6, T. 42S, R. 19E,

Well No. Nordeen #3  
Sec. 5, T. 42S, R. 19E,

Well No. Utah #1  
Sec. 7, T. 42S, R. 19E,  
San Juan County, Utah

Gentlemen:

In reference to your letter of February 20, 1979 on the above wells, our files show these wells have already been drilled to a shallow depth, but with no further notices of what happened to them.

However, if and when you desire to assume operations, please send a letter to this effect, and they will be covered under Williams Ranches Blanket Bond. Notify us verbally when you do start drilling, and follow up with Sundry Notices.

Sincerely yours,

DIVISION OF OIL, GAS, AND MINING

*Kathy Avila*

KATHY AVILA  
RECORDS CLERK



THE TRAVELERS

030201

CHANGE RIDER

BOND NO. 490E867A	ON BEHALF OF Williams Ranches, Inc.	
DATE OF BOND 12-28-77	IN FAVOR OF State of Utah, Oil and Gas Conservation Commission	
ADDITIONAL PREMIUM \$ 00.00	RETURN PREMIUM \$ 00.00	EFFECTIVE DATE OF CHANGE March 1, 1980

This rider is to be attached to and form a part of the above described bond.

In consideration of the additional or return premium shown above the surety hereby gives its consent to \_\_\_\_\_

to change the name from: Williams Ranches, Inc.

to: San Juan Minerals Exploration Company

will be Utah No 1 7, 425, 19E  
43-037-30101

Provided, however, that the aggregate liability of the surety for any one or more losses occurring prior to the effective date of change shall not exceed ~~20,000.00~~, or for any one or more losses occurring after said date exceed 50,000.00. It is further understood that in no event shall the surety's liability be cumulative.

Signed and dated on March 1, 1980  
(Month, day, year)

THE TRAVELERS INDEMNITY COMPANY

By Jane A. Carmichael  
(Attorney in fact)  
Jane A. Carmichael

Accepted

San Juan Minerals Exploration Company

Jack Williams Pres

COMPANY: WILLIAMS RANCHES UT ACCOUNT # 113280 SUSPENSE DATE: \_\_\_\_\_

TELEPHONE CONTACT DOCUMENTATION

CONTACT NAME: Jill Johnson 11:40 11-25 NO ANSWER  
CONTACT TELEPHONE NO.: 1-619-922-4422 (Blythe, Ca) 11-26 11:40 NO ANSWER

SUBJECT: Utah #1 4303730101 7 425 19E  
Nardeen 3 4303730108 5 425 19E  
Nardeen 1-A 4303730128 6 425 19E  
Nardeen 2-A 4303730161 6 425 19E

I PAID on just  
PPAID them but  
didn't have any  
valid reason.

(Use attachments if necessary)

RESULTS: leases  
these wells were purchased from Shiprock  
in 1978. Jill has hardly any info on these  
wells and wouldn't know what to  
file to give us any info.

NOW WHAT? ANY BODY'S GUESSES  
(Use attachments if necessary)

CONTACTED BY: UC  
DATE: Dec 11, 1986

From the desk of  
NORM STOUT

VICK,

... SHORT OF INSPECTOR FIELD REPORTS,  
I KNOW OF NO REASON THESE SHOULD  
NOT BE EITHER ~~ON~~ EUS, OR  
ON THE TAD WITH WILLIAMS  
RANCHES AS OPERATOR.

*Norm*

12-12-86

November 22, 1988

TO: Tami Searing  
Lisha Romero

FROM: Don Staley

RE: Change of Well Data

At the decision of the Well Review Committee which met today, please make the following well data changes:

- \*\* Utah Southern 1, API No. 43-037-30101
  - Change the well status from OPS to SOW so that the well will begin showing up on San Juan Mineral's 'Turn-around document'.
  - Assign Entity number (currently 99999).
- \*\* Nelwyn Nordeen 3, API No. 43-037-30108
  - Change the well status from OPS to SOW so that the well will begin showing up on San Juan Mineral's 'Turn-around document'.
  - Assign Entity number (currently 99999).
- \*\* Nordeen 1-A, API No. 43-037-30128
  - Change the well status from OPS to SOW so that the well will begin showing up on San Juan Mineral's 'Turn-around document'.
  - Assign Entity number (currently 99999).
- \*\* Nordeen 2-A, API No. 43-037-30161
  - Change the well operator from Williams Ranches Inc. (N3280) to San Juan Minerals (N0810).
  - Change the well status from OPS to SOW so that the well will begin showing up on San Juan Mineral's 'Turn-around document'.
  - Assign Entity number (currently 99998).

These wells were all originally drilled by Delta Company and Schurr-Dickinson-Gregg Oil Company. The wells were then apparently sold to Shiprock Oil and then to Williams Ranches which later became San Juan Minerals. Documentation exists in the well files that shows that Williams Ranches wasn't sure what they bought from Shiprock, and that they stated that they did buy "these leases". We would like to make it clear to San Juan Minerals that they are responsible for these wells and that we will hold them accountable. Therefore we are putting the wells on the company's production report to see what kind of response we get back.

Please let me know when these changes have been made. Thanks.

cc: R.J. Firth  
A.W. Sollis  
V.L. Carney  
P.M. Kenna

Well File - Utah Southern 1 (7-42S-19E, San Juan Co.)  
Well File - Nelwyn Nordeen 3 (5-42S-19E, San Juan Co.)  
Well File - Nordeen 1-A (6-42S-19E, San Juan Co.)  
Well File - Nordeen 2-A (6-42S-19E, San Juan Co.)

WELL REVIEW COMMITTEE - Notes  
Meeting held 11-22-88

Well File  
Utah Southern 1  
(7-425-19E  
San Juan)

Reviewed progress on wells presented to Committee at 10-5-88 meeting:

- \* State 16-6 (API 43-013-31145)  
Sent letter to Ed Bonner of State Lands on 10-21-88. Advised State Lands that they, as lessor, are responsible for the final resolution of this wells problems. Met with Ed Bonner on 11-16-88. He said that he is currently working with CKM Resources to get the problems on this well resolved.
- \* Gerald Young Ranch 1 (API 43-043-30049)  
According to research performed by Arlene Sollis, a \$5000 certificate of deposit exists for the well which expire mid-January, 1989. She has contacted both Mr. Naylor (Combined Oil and Gas) and Mr. Sid Tomlinson (claims to be the new operator). Neither party seems to be doing much to resolve the problem. Tomlinson has been in touch with John Baza in the past few weeks to talk about plugging the well. In the meantime, the Committee feels that there isn't much we can do other than try to get a replacement bond before the certificate of deposit expires in January. Don Staley was asked to write a letter to the operator of record - Naylor - and tell him he is still responsible for the well until the new operator get a bond and that we will call him before the board if he doesn't comply.
- \* Needles Anticline 1-B (API 43-027-30011)  
Sent letter to Ed Bonner of State Lands on 10-21-88. Advised State Lands that they, as lessor, are responsible for the final resolution of this wells problems. Met with Ed Bonner on 11-16-88. He said that he is checking with State Land's attorney to see if they can use a certificate of deposit that's on file for the well to reclaim the location.
- \* Bitter Creek Unit 63-2 (API 43-047-11477)  
Sent letter to Ed Bonner of State Lands on 10-21-88. Advised State Lands that they, as lessor, are responsible for the final resolution of this wells problems. Met with Ed Bonner on 11-16-88. He said that he hasn't done anything with this well yet, but felt there probably isn't anything State Lands would be able to do. Don Staley was asked at this meeting to show some inspection pictures to Ed which show how messy the location is.
- \* Harrison Federal 31-1 (API 43-019-30339)  
This well was PxA'd. No committee action required.

Discussed new wells:

- \* Anschutz Ranch East 6-30U (API 43-043-30177)  
Ron Firth requested that Amoco's W30-06 be fixed to reflect the correct name of W30-06A in order to prevent confusion with the Anschutz well. Don Staley checked the Amoco well file and found that Amoco had actually changed the name of the well to the W30-06. So, no action was taken on that matter. According to conversations that Arlene Sollis had with Amoco and Anschutz, the well may be plugged. Anschutz is supposedly sending in a plugging report to us. Jimmie Thompson will send an inspector out to check it out. Ron Firth said that if Anschutz doesn't have any more wells we ought to let

them know that we will relinquish the bond if they request it. They can then get a new bond if they drill more wells.

- \* Stephen Szot 1 (API 43-005-30009)  
Mrs. Szot visited Jimmie Thompson about 6 months ago to discuss all the legal problems concerning this well. The law suit between the Szots and Delta Petroleum is still in progress. Jimmie was in touch with attorney Alan Bachman who said there was nothing the Division can do. Jimmie will be sending a copy of a letter he has prepared concerning this matter to the well file.
- \* Stephen Szot 2 (API 43-005-30010)  
Same as Stephen Szot 1 above.
- \* Nordeen 1-A (API 43-037-30128)  
It was concluded by the Committee that the main thing that needs to take place concerning this well is to get San Juan Minerals to accept responsibility for the well. San Juan (formerly Williams Ranches) said that they took over the wells from Shiprock Oil, but didn't receive any records and weren't too sure what they bought. The Committee concluded that the well's computer status ought to be changed from OPS to SOW so that the well would begin showing up on San Juan's 'turn-around document'. In doing some research, Don Staley found three other San Juan Minerals wells that fall into this same scenario: Utah Southern 1 (API 43-037-30101), Nelwyn Nordeen 3 (43-037-30108), and the Nordeen 2-A (API 43-037-30161). Don Staley gained Ron Firth's approval to have them begin showing up on San Juan's report also. A memo was sent to Tami Searing and Lisha Romero to change the necessary data in the computer to have the wells begin showing up on the 'turn-around document'.
- \* Natural Buttes Unit 82N4 (formerly NBU 82J) (API 43-047-31236)  
According to reports that have been sent in on this well, the well may have been PxA'd. John Baza will check on this and report back at the next Well Review Committee meeting.

Also discussed:

- \* John Baza proposed the need for us to push for new legislation or a rule change that makes it possible for ownership of old fee and state lease wells to revert back to the surface owner after a certain length of time if problems cannot be resolved. John Baza will do some research on how other states handle this problem and return to the Committee with some proposals.
- \* The feasibility of setting up Field files was discussed. It was concluded that the Administrative group would be in charge of filing such materials, and that some filing cabinets for that purpose would be set up in Millie Sollis' old office. Millie's old office will become a file room overflow area. The Unit files, Plant files, and any other miscellaneous files of that nature may be housed there.
- \* It was decided that we ought to be more conscientious about sending information to the well file and that the Telephone Documentation Form ought to be used more. Don Staley will look into updating the form, making it a 'portrait' form instead of a 'landscape' form, and making the form more available.

DTS (11-23-88)

cc: R.J. Firth  
J.R. Baza  
S.L. Schneider  
G.L. Hunt  
A.W. Sollis  
J.L. Thompson

Well File - State 16-6 (16-9S-17E, Duchesne Co.)  
Well File - Gerald Young Ranch 1 (30-1S-6E, Summit Co.)  
Well File - Needles Anticline State 1-B (Millard Co.)  
Well File - Bitter Creek Unit 63-2 (2-10S-21E, Uintah Co.)  
Well File - Harrison Federal 31-1 (31-20S-24E, Grand Co.)  
Well File - Anschutz Ranch East 6-30U (30-4N-8E, Summit Co.)  
Well File - Stephen Szot 1 (19-14N-1E, Cache Co.)  
Well File - Stephen Szot 2 (19-14N-1E, Cache Co.)  
Well File - Nordeen 1-A (6-42S-19E, San Juan Co.)  
Well File - Natural Buttes Unit 82N4 (26-9S-21E, Uintah Co.)  
Well File - Utah Southern 1 (7-42S-19E, San Juan Co.)  
Well File - Nelwyn Nordeen 3 (5-42S-19E, San Juan Co.)  
Well File - Nordeen 2-A (6-42S-19E, San Juan Co.)

Division of Oil, Gas and Mining  
PHONE CONVERSATION DOCUMENTATION FORM

RECEIVED  
DEC 27 1989

Route original/copy to:

Well File \_\_\_\_\_

Suspense  
(Return Date) \_\_\_\_\_

DIVISION OF  
OIL, GAS & MINES  Other

(Location) Sec 5-7 Twp 42S Rng 19E

(To - Initials) \_\_\_\_\_

(API No.) 43-037-30103 - 31256 - 3024 - 30101

1. Date of Phone Call: 12/20/89 Time: 8 48 AM

2. DOGM Employee (name) Glenn Goodwin (Initiated Call   
Talked to:

Name Mrs. Williams (Initiated Call  - Phone No. (619) 922-2222

of (Company/Organization) San Juan Minerals

3. Topic of Conversation: Well sign's - Norden 3 - Norden - 86-10 - Norden 2  
Utah #1

4. Highlights of Conversation: 30 days to install signs &  
well that are T&A Put caps or valves on well  
so they will not be open for something to  
step in.

# SAN JUAN MINERALS EXPLORATION COMPANY

ROUTE 1, BOX 52

BLYTHE, CALIFORNIA 92225

April 16, 1992

**RECEIVED**

APR 23 1992

**DIVISION OF  
OIL, GAS & MINING**

Mr. Mike Hebertson  
Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Dear Mr. Hebertson:

In response to the March 10, 1992 letter and a later telephone conversation, I have been trying to up-date our well records.


I still have not been able to locate well-site descriptions for the following wells:

Nordeen #1	43	03720721	May 22 - 12/91
Nordeen #5	43	03720722	6/92 - 12/91
Nordeen Fee #3	43	03730149	NE NW SEC 5 T19S 19E
Utah #1	43	03730101	NW SW SEC. 42S 19E
Nordeen #2-A	43	03730161	NE NW SEC 5 T19S 19E


We are uncertain how to accurately report on these wells because we are not sure where they are located. Any information your office has on these wells may help us to reconcile our records.

We are fairly certain Nordeen #2-A is an old abandoned well. We feel this way because we do not have any wells (Nordeen) in Section 6. Any information you have will be appreciated.

Sincerely,

  
Jill Johnson

13  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100  
101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200  
201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300  
301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400  
401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500  
501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600  
601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700  
701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800  
801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
841  
842  
843  
844  
845  
846  
847  
848  
849  
850  
851  
852  
853  
854  
855  
856  
857  
858  
859  
860  
861  
862  
863  
864  
865  
866  
867  
868  
869  
870  
871  
872  
873  
874  
875  
876  
877  
878  
879  
880  
881  
882  
883  
884  
885  
886  
887  
888  
889  
890  
891  
892  
893  
894  
895  
896  
897  
898  
899  
900  
901  
902  
903  
904  
905  
906  
907  
908  
909  
910  
911  
912  
913  
914  
915  
916  
917  
918  
919  
920  
921  
922  
923  
924  
925  
926  
927  
928  
929  
930  
931  
932  
933  
934  
935  
936  
937  
938  
939  
940  
941  
942  
943  
944  
945  
946  
947  
948  
949  
950  
951  
952  
953  
954  
955  
956  
957  
958  
959  
960  
961  
962  
963  
964  
965  
966  
967  
968  
969  
970  
971  
972  
973  
974  
975  
976  
977  
978  
979  
980  
981  
982  
983  
984  
985  
986  
987  
988  
989  
990  
991  
992  
993  
994  
995  
996  
997  
998  
999  
1000



PHOTOGEOLOGIC MAP  
SAN JUAN MINERALS EXPLORATION COMP  
MEXICAN HAT AREA  
SAN JUAN COUNTY, UTAH Scale 1"=20'



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING -

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

File

April 27, 1992

Jill Johnson  
San Juan Minerals Exploration Company  
Route 1, Box 52  
Blythe, California 92225

Dear Ms. Johnson:

Re: Information Request

The following information from our files and Database may help to solve the questions that exist about five wells owned by San Juan Minerals.

Nordeen Fee #3, 43-037-30149 is supposed to be located NE NW, Section 5, T. 42S, R. 19E, 1110' FNL 1739' FWL. It's carried in our Database as a producing oil well and has production reported by San Juan Minerals through December 1991.

Utah #1, 43-037-30101 is supposed to be located NW SW, Section 7, T. 42S, R. 19E, 1844' FSL 839' FWL. It's carried in our Database as a producing oil well and has production reported by San Juan Minerals through December 1991.

Nordeen #2-A, 43-037-30161 is supposed to be located NE NW, Section 6, T. 42S, R. 19E, 776' FNL 1371' FWL. It is carried in our Database as a producing oil well and has production reported by San Juan Minerals through December 1991.

At this point it would be appropriate to point out that any well, once it has been abandoned, cannot have production allocated to it. Therefore, any of the above wells that are plugged will have to have an amended production report filed, and a plugging report filed on a Sundry Notice.

The only information that was found referring to Nordeen #1, 43-037-20721 and Nordeen #5, 43-037-20722 is a map supplied by San Juan Minerals with possible locations noted for these wells. According to a field inspection, the Nordeen #1 has a production tank and pump jack on location. The tank identifies this well as the Nordeen #1.

Page 2  
San Juan Minerals Exploration Company  
April 27, 1992

The question still remains; where are the actual locations of the Nordeen #1 and Nordeen #5 both of which are listed as producing oil wells.

Should this information not clear up the outstanding questions about the above referenced wells, it will be necessary to submit a certified survey plat for these wells.

Sincerely,

A handwritten signature in cursive script that reads "Frank R. Matthews". The signature is written in dark ink and is positioned above the typed name and title.

Frank R. Matthews  
Petroleum Engineer

ldc  
cc: R.J. Firth  
WO11

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING

SEE INSTRUCTIONS ON REVERSE SIDE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
San Juan Minerals Exploration Co.

3. ADDRESS OF OPERATOR  
10970 Williams ave Blythe, CA 92225

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1844' SL and 839' WL

14. PERMIT NO.  
43 037 30101

15. ELEVATIONS (Show whether OF, BY, OR, OR.)  
4275 gr

5. LEASE DESIGNATION AND SERIAL NO.  
fee

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Nordeen

9. WELL NO.  
Utah #1

10. FIELD AND POOL, OR WILDCAT  
Mexican Hat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 6 or 7 ?  
T42S R 19 E

12. COUNTY OR PARISH 13. STATE  
San Juan UT

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

16. NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	<i>WATER SHUT-OFF</i>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your letter of April 27, 1992. We are updating our records and researching our well files.

We do not even know where this well is. I have found some old paperwork on it filed by Schurr Dickinson Gregg Oil Co. It has the above well location site but shows the application being for Section 6 not Section 7 as shown records show.

We are certainly not producing oil at this well location in Section 6 or 7. I have enclosed a copy of the application I came across. That is the extend of my information on this well.

RECEIVED

MAY 15 1992

DIVISION OF  
OIL GAS & MINING

18. I hereby certify that the foregoing is true and correct

SIGNED *Julie Johnson* TITLE Secretary DATE 5-12-92

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

# SAN JUAN MINERALS EXPLORATION COMPANY

ROUTE 1, BOX 52

BLYTHE, CALIFORNIA 92225

September 24, 1992

Ms. Debra Eatchel  
Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, UT 84180-1203

Dear Debra:

I have enclosed the three Sundry Notices you requested in our telephone conversation today. I have no information on the Nordeen 1A, as we have never used this well.

The Utah Nordeen #1 is also an abandoned well. It is another well that we have no current information on. We have never drilled or performed work on this well site.

The Nordeen #7 in Section 5 - 1110'NL and 2402'WL and the API number 43 037 30419 is an abandoned well. I feel that this is your 43 037 30194, as shown on the Monthly Oil and Gas Report.

We do have an old well in Section 8 as explained in the Sundry Notice. This well is shut-in. I think it needs to be added to the Oil and Gas Report as Nordeen #7 in Section 8. And the Nordeen #7 in Section 5, needs to be removed.

Sincerely,

  
Bill Johnson

RECEIVED

SEP 28 1992

DIVISION OF  
OIL GAS & MINING

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS, AND MINING

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
San Juan Minerals Exploration Co.

3. ADDRESS OF OPERATOR  
10970 Williams ave Blythe, CA 92225

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface  
1844' SL and 839' WL

14. PERMIT NO.  
43 037 30101

15. ELEVATIONS (Show whether OF, BT, OR, etc.)  
4275 gr

5. LEASE DESIGNATION AND SERIAL NO.  
fee

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Nordeen

9. WELL NO.  
Utah #1

10. FIELD AND POOL, OR WILDCAT  
Mexican Hat

11. SEC., T., R., M., OR BLK. AND SUBST OR ARRA  
Sec T42S R 19 E

12. COUNTY OR PARISH  
San Juan

13. STATE  
UT

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	FULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In response to your letter of April 27, 1992. We are updating our records and researching our well files.

We do not even know where this well is. I have found some old paperwork on it filed by Schurr Dickinson Gregg Oil Co. It has the above well location site but shows the application being for Section 6 not Section 7 as shown records show.

We are certainly not producing oil at this well location in Section 6 or 7. I have enclosed a copy of the application I came across. That is the extent of my information on this well.

RECEIVED

SEP 28 1992

DIVISION OF OIL, GAS & MINING

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Secretary DATE 5-12-92

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

FORM 9

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter plugged wells, or to drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals.

1. TYPE OF WELL OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER _____		5. LEASE DESIGNATION AND SERIAL NUMBER:
2. NAME OF OPERATOR: San Juan Minerals Exploration Inc. <i>N0810</i>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME:
3. ADDRESS OF OPERATOR: Hwy 163 P.O. Box 310367 Mexican Hat Ut 84531		7. UNIT or CA AGREEMENT NAME:
4. LOCATION OF WELL FOOTAGES AT SURFACE: QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN:		8. WELL NAME and NUMBER: see attached list
PHONE NUMBER: (435) 683-2298		9. API NUMBER:
COUNTY: San Juan		10. FIELD AND POOL OR WILDCAT: Mexican Hat
STATE: UTAH		

11. CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input type="checkbox"/> NOTICE OF INTENT (Submit in Duplicate) Approximate date work will start: _____	<input type="checkbox"/> ACIDIZE	<input type="checkbox"/> DEEPEN	<input type="checkbox"/> REPERFORATE CURRENT FORMATION
<input type="checkbox"/> SUBSEQUENT REPORT (Submit Original Form Only) Date of work completion: _____	<input type="checkbox"/> ALTER CASING	<input type="checkbox"/> FRACTURE TREAT	<input type="checkbox"/> SIDETRACK TO REPAIR WELL
	<input type="checkbox"/> CASING REPAIR	<input type="checkbox"/> NEW CONSTRUCTION	<input type="checkbox"/> TEMPORARILY ABANDON
	<input type="checkbox"/> CHANGE TO PREVIOUS PLANS	<input type="checkbox"/> OPERATOR CHANGE	<input type="checkbox"/> TUBING REPAIR
	<input type="checkbox"/> CHANGE TUBING	<input type="checkbox"/> PLUG AND ABANDON	<input type="checkbox"/> VENT OR FLARE
	<input type="checkbox"/> CHANGE WELL NAME	<input type="checkbox"/> PLUG BACK	<input type="checkbox"/> WATER DISPOSAL
	<input type="checkbox"/> CHANGE WELL STATUS	<input type="checkbox"/> PRODUCTION (START/RESUME)	<input type="checkbox"/> WATER SHUT-OFF
	<input type="checkbox"/> COMMINGLE PRODUCING FORMATIONS	<input type="checkbox"/> RECLAMATION OF WELL SITE	<input checked="" type="checkbox"/> OTHER: <u>change of operator</u>
	<input type="checkbox"/> CONVERT WELL TYPE	<input type="checkbox"/> RECOMPLETE - DIFFERENT FORMATION	

12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly show all pertinent details including dates, depths, volumes, etc.

San Juan Minerals Exploration Inc. is transferring operation of its oil wells in San Juan County at Mexican Hat, (see attached List ) To: Wesgra Corporation P.O. Box 310367 Mexican Hat Ut. 84531. Wesgra Corporation Is Bonded By Letter of credit # 7230. Would like to make this change effective as of April 30 2006

Wesgra Corporation:  
by: Clint Howell President *N1060*  
*Clint Howell*  
April /20/ 2006

NAME (PLEASE PRINT) Clint Howell TITLE President  
SIGNATURE *Clint Howell* DATE 4/20/2006

(This space for State use only)

APPROVED 513106  
*Earlene Russell*  
Division of Oil, Gas and Mining  
Earlene Russell, Engineering Technician

(5/2000)

(See Instructions on Reverse Side)

RECEIVED  
APR 24 2006

DIV. OF OIL, GAS & MINING

San Juan Minerals (N0810) to Wesgra Corporation (N1060)

well name	api	qtr	qtr	sec	twsp	rng	well	stat	l_num
GEBAUER FEDERAL 2	4303730190	SENE		07	420S	190E	OW	S	UTU-7303
SUTHERLAND FEDERAL 97-4	4303731784	NESW		05	420S	190E	OW	S	UTU-7303D
NORDEEN 1	4303720721	NENW		05	420S	190E	OW	S	FEE
NORDEEN 5	4303720722	SWNW		05	420S	190E	OW	P	FEE
NORDEEN 3	4303730149	NENW		05	420S	190E	OW	P	FEE
WILM RNCH GDRDGE 12	4303730432	NWNW		08	420S	190E	OW	P	FEE
GOODRIDGE 74	4303730526	NWNW		08	420S	190E	OW	S	FEE
GOODRIDGE 75	4303730527	NWNW		08	420S	190E	OW	S	FEE
GOODRIDGE 80.2	4303730561	NWNW		08	420S	190E	OW	P	FEE
GOODRIDGE 80.3	4303730562	NWNW		08	420S	190E	OW	P	FEE
GOODRIDGE 80.4	4303730563	NWNW		08	420S	190E	OW	P	FEE
GOODRIDGE 80.1	4303730570	NWNW		08	420S	190E	OW	S	FEE
NORDEEN 80.7	4303730584	SESW		05	420S	190E	OW	P	FEE
NORDEEN 80.6	4303730585	SESW		05	420S	190E	OW	S	FEE
GOODRIDGE 80.5	4303730680	NWNW		08	420S	190E	OW	P	FEE
NORDEEN 81-4	4303730957	SWSW		05	420S	190E	OW	S	FEE
NORDEEN 81-5	4303730958	SWSW		05	420S	190E	OW	S	FEE
GOODRIDGE 81-3	4303730960	SENE		07	420S	190E	OW	S	FEE
J & L 3	4303731207	NWSW		06	420S	190E	OW	TA	FEE
NORDEEN 86-6	4303731254	SENW		05	420S	190E	OW	S	FEE
GOODRIDGE 91-2	4303731605	SENE		07	420S	190E	OW	S	FEE
GOODRIDGE 91-7	4303731613	SWNW		08	420S	190E	OW	S	FEE
GOODRIDGE 91-16	4303731634	NENE		07	420S	190E	OW	S	FEE
GOODRIDGE 91-12	4303731637	NENE		07	420S	190E	OW	S	FEE
GOODRIDGE 1	4303731647	SENE		07	420S	190E	OW	S	FEE
J&L 3-X	4303731669	NESW		06	420S	190E	OW	S	FEE
DICKENSON/HOWARD 1	4303731845	NWSW		05	420S	190E	OW	NEW	FEE
UTAH 1	4303730101	NWSW		07	420S	190E	OW	PA	FEE
NELWYN A NORDEEN 2	4303730104	SENW		05	420S	190E	OW	PA	FEE
NELWYN NORDEEN 3	4303730108	SENW		05	420S	190E	OW	PA	FEE
NORDEEN 1A	4303730128	NENW		06	420S	190E	OW	PA	FEE
NORDEEN 2-A	4303730161	NENW		06	420S	190E	OW	PA	FEE
NORDEEN 7	4303730194	NENW		05	420S	190E	OW	PA	FEE
NORDEEN 11	4303730480	SWSW		05	420S	190E	D	PA	FEE
NORDEEN 80.13	4303730581	SESW		05	420S	190E	D	PA	FEE
GOODRIDGE 81-1	4303730961	SWNW		08	420S	190E	OW	PA	FEE
GOODRIDGE 71	4303730968	NWNW		08	420S	190E	D	PA	FEE
NORDEEN 86-4	4303731253	SENW		05	420S	190E	D	PA	FEE
NORDEEN 86-8	4303731255	SWNE		05	420S	190E	OW	PA	FEE
NORDEEN 86-10	4303731256	SENW		05	420S	190E	OW	PA	FEE
CROSSING NO 2 8	4303731445	SWSE		07	420S	190E	OW	PA	FEE
CROSSING NO 2 12	4303731446	SWSE		07	420S	190E	OW	PA	FEE
GOODRIDGE 91-10	4303731609	NENE		07	420S	190E	OW	PA	FEE
GOODRIDGE 91-5	4303731611	SENE		07	420S	190E	D	PA	FEE
GOODRIDGE 91-4	4303731614	SENE		07	420S	190E	OW	PA	FEE
GOODRIDGE 2	4303731640	NWNW		08	420S	190E	OW	PA	FEE
GOODRIDGE 92-3	4303731652	NWNE		07	420S	190E	OW	PA	FEE

**OPERATOR CHANGE WORKSHEET**

**ROUTING**

1. DJJ
2. CDW

Change of Operator (Well Sold)

Designation of Agent/Operator

**X Operator Name Change**

Merger

The operator of the well(s) listed below has changed, effective:

**4/30/2006**

<b>FROM: (Old Operator):</b> N0810-San Juan Minerals Exploration Inc. Hwy 163 PO Box 310367 Mexican Hat, UT 84531 Phone: 1-(435) 683-2298	<b>TO: (New Operator):</b> N1060-Wesgra Corporation PO Box 310367 Mexican Hat, UT 84531 Phone: 1-(435) 683-2298
---	---

CA No.

Unit:

**WELL(S)**

NAME	SEC	TWN	RNG	API NO	ENTITY NO	LEASE TYPE	WELL TYPE	WELL STATUS
NELWYN A NORDEEN 2	05	420S	190E	4303730104	490	Fee	OW	PA
NELWYN NORDEEN 3	05	420S	190E	4303730108	10950	Fee	OW	PA
NORDEEN 7	05	420S	190E	4303730194	490	Fee	OW	PA
NORDEEN 11	05	420S	190E	4303730480	99998	Fee	D	PA
NORDEEN 80.13	05	420S	190E	4303730581	99998	Fee	D	PA
NORDEEN 86-4	05	420S	190E	4303731253	490	Fee	D	PA
NORDEEN 86-8	05	420S	190E	4303731255	490	Fee	OW	PA
NORDEEN 86-10	05	420S	190E	4303731256	490	Fee	OW	PA
NORDEEN 1A	06	420S	190E	4303730128	10950	Fee	OW	PA
NORDEEN 2-A	06	420S	190E	4303730161	10950	Fee	OW	PA
UTAH 1	07	420S	190E	4303730101	10950	Fee	OW	PA
CROSSING NO 2 8	07	420S	190E	4303731445	10908	Fee	OW	PA
CROSSING NO 2 12	07	420S	190E	4303731446	10691	Fee	OW	PA
GOODRIDGE 91-10	07	420S	190E	4303731609	11206	Fee	OW	PA
GOODRIDGE 91-5	07	420S	190E	4303731611	11206	Fee	D	PA
GOODRIDGE 91-4	07	420S	190E	4303731614	11206	Fee	OW	PA
GOODRIDGE 92-3	07	420S	190E	4303731652	11206	Fee	OW	PA
GOODRIDGE 81-1	08	420S	190E	4303730961	99998	Fee	OW	PA
GOODRIDGE 71	08	420S	190E	4303730968	99998	Fee	D	PA
GOODRIDGE 2	08	420S	190E	4303731640	11260	Fee	OW	PA

**OPERATOR CHANGES DOCUMENTATION**

Enter date after each listed item is completed

- (R649-8-10) Sundry or legal documentation was received from the **FORMER** operator on: 4/24/2006
- (R649-8-10) Sundry or legal documentation was received from the **NEW** operator on: 4/24/2006
- The new company was checked on the **Department of Commerce, Division of Corporations Database** on: 4/26/2006
- Is the new operator registered in the State of Utah: YES Business Number: 670418-0142
- If **NO**, the operator was contacted on:
- a. (R649-9-2)Waste Management Plan has been received on: requested 4/26
- b. Inspections of LA PA state/fee well sites complete on: moving PA fee wells to new company
- c. Reports current for Production/Disposition & Sundries on: 5/1/2006

7. **Federal and Indian Lease Wells:** The BLM and or the BIA has approved the merger, name change, or operator change for all wells listed on Federal or Indian leases on: not yet

8. **Federal and Indian Units:**

The BLM or BIA has approved the successor of unit operator for wells listed on: n/a

9. **Federal and Indian Communization Agreements ("CA"):**

The BLM or BIA has approved the operator for all wells listed within a CA on: n/a

10. **Underground Injection Control ("UIC")** The Division has approved UIC Form 5, **Transfer of Authority to Inject**, for the enhanced/secondary recovery unit/project for the water disposal well(s) listed on: n/a

**DATA ENTRY:**

1. Changes entered in the Oil and Gas Database on: 5/3/2006
2. Changes have been entered on the Monthly Operator Change Spread Sheet on: 5/3/2006
3. Bond information entered in RBDMS on: 5/3/2006
4. Fee/State wells attached to bond in RBDMS on: 5/3/2006
5. Injection Projects to new operator in RBDMS on: n/a
6. Receipt of Acceptance of Drilling Procedures for APD/New on: merger

**FEDERAL WELL(S) BOND VERIFICATION:**

1. Federal well(s) covered by Bond Number: \_\_\_\_\_

**INDIAN WELL(S) BOND VERIFICATION:**

1. Indian well(s) covered by Bond Number: n/a

**FEE & STATE WELL(S) BOND VERIFICATION:**

1. (R649-3-1) The **NEW** operator of any fee well(s) listed covered by Bond Number 007230

2. The **FORMER** operator has requested a release of liability from their bond on: 4/24/2006  
The Division sent response by letter on: moving PA fee wells to new company

**LEASE INTEREST OWNER NOTIFICATION:**

3. (R649-2-10) The **FORMER** operator of the fee wells has been contacted and informed by a letter from the Division of their responsibility to notify all interest owners of this change on: 5/4/2006

**COMMENTS:**

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_