

## UTAH OIL AND GAS CONSERVATION COMMISSION

REMARKS WELL LOG  ELECTRIC LOGS  FILE  WATER SANDS  LOCATION INSPECTED  SUB REPORT/abd

*Application resubmitted 6.6.85*

DATE FILED 11-21-83

LAND: FEE & PATENTED  STATE LEASE NO

PUBLIC LEASE NO

INDIAN

DRILLING APPROVED: 11-22-83 - OIL (CAUSE NO. 156-3)

SPUDDED IN: *1-15-84 - Report called in. Company claims well not drilled. \* Sec 10-18-91 Insp.*

COMPLETED: PUT TO PRODUCING

INITIAL PRODUCTION

GRAVITY A.P.I.

GOR

PRODUCING ZONES:

TOTAL DEPTH:

WELL ELEVATION:

DATE ABANDONED: ~~11-6-83~~ 7-6-85

FIELD: 3/46 MEXICAN HAT

UNIT

COUNTY: SAN JUAN

WELL NO. GOODRIDGE 81-2

API #43-037-30959

LOCATION 2373' FNL FT FROM (N) (S) LINE. 94' FEL

FT FROM (E) (W) LINE

SENE

1/4 - 1/4 SEC.

7

TWP

RGE

SEC

OPERATOR

TWP

RGE

SEC

OPERATOR

✓ 42S 19E 7 SAN JUAN MINERALS EXPLOR.




COMPANY WILLIAMS RANCHES

LEASE \_\_\_\_\_ WELL NO. 81-2

SEC. 7 .T. 42 SOUTH .R. 19 EAST, S. L. M.,

LOCATION 2373 FEET FROM THE NORTH LINE AND  
94 FEET FROM THE EAST LINE

ELEVATION 4146 UNGRADED GROUND



SCALE - 1 INCH EQUALS 1000 FEET

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEYS MADE BY ME UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

SEAL:

  
Registered Land Surveyor.  
James P. Leese  
Utah Reg. LS #1472

SURVEYED September 16, . 19 81

OPERATOR SAN JUAN MINERALS EXPLORATION CO DATE 11-21-83

WELL NAME GOODRIDGE 81-2

SEC SENE 7 T 42S R 19E COUNTY SAN JUAN

43-037-30959  
API NUMBER

FEE  
TYPE OF LEASE

POSTING CHECK OFF:

<input type="checkbox"/>	INDEX	<input type="checkbox"/>	MAP	<input type="checkbox"/>	HL
<input type="checkbox"/>	NID	<input type="checkbox"/>		<input type="checkbox"/>	PI

PROCESSING COMMENTS:

WATER OK

APPROVED BY THE STATE  
OF UTAH DIVISION OF  
OIL, GAS, AND MINING  
DATE: 11-21-83  
BY: [Signature]

CHIEF PETROLEUM ENGINEER REVIEW:

11/21/83

APPROVAL LETTER:

SPACING:  A-3 \_\_\_\_\_ UNIT  c-3-a 156-3 4-15-80  
CAUSE NO. & DATE

c-3-b  c-3-c

SPECIAL LANGUAGE:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

RECONCILE WELL NAME AND LOCATION ON APD AGAINST SAME DATA ON PLAT MAP.

AUTHENTICATE LEASE AND OPERATOR INFORMATION

VERIFY ADEQUATE AND PROPER BONDING

AUTHENTICATE IF SITE IS IN A NAMED FIELD, ETC.

APPLY SPACING CONSIDERATION

ORDER 156-3

UNIT \_\_\_\_\_

c-3-b

c-3-c

CHECK DISTANCE TO NEAREST WELL.

CHECK OUTSTANDING OR OVERDUE REPORTS FOR OPERATOR'S OTHER WELLS.

IF POTASH DESIGNATED AREA, SPECIAL LANGUAGE ON APPROVAL LETTER

IF IN OIL SHALE DESIGNATED AREA, SPECIAL APPROVAL LANGUAGE.

VERIFY LEGAL AND SUFFICIENT DRILLING WATER

November 21, 1983

San Juan Minerals Exploration Company  
Rt. 1 Box 52  
Blythe, California 92225

RE: Well No. Goodridge 81-2  
SENE Sec. 7, T. 42S, R. 19E  
2373 FNL, 24' FWL  
San Juan County, Utah

Gentlemen:

Insofar as this office is concerned, approval to drill the above referred to oil well is hereby granted in accordance with the Order issued in Cause No. 156-3 dated April 15, 1980.

Should you determine that it will be necessary to plug and abandon this well, you are hereby requested to immediately notify the following:

RONALD J. FIRTH - Chief Petroleum Engineer  
Office: 533-5771  
Home: 571-6068

Enclosed please find Form OGC-8-X, which is to be completed whether or not water sands (aquifers) are encountered during drilling. Your cooperation in completing this form will be appreciated.

Further, it is requested that this Division be notified within 24 hours after drilling operations commence, and that the drilling contractor and rig number be identified.

The API number assigned to this well is 43-037-30959.

Sincerely,

  
Norman C. Stout  
Administrative Assistant

NCS/as  
Encl.

DIVISION OF OIL, GAS AND MINING

SPUDDING INFORMATION

NAME OF COMPANY: SAN JUAN MINERALS

WELL NAME: GOODRIDGE 81-2

SECTION SENE 7 TOWNSHIP 42S RANGE 19E COUNTY San Juan

DRILLING CONTRACTOR A-1 Drilling

RIG # 11

SPUDED: DATE 1-15-84

TIME \_\_\_\_\_

How \_\_\_\_\_

DRILLING WILL COMMENCE \_\_\_\_\_

REPORTED BY Jill Johnson

TELEPHONE # \_\_\_\_\_

DATE 1-18-84 SIGNED RJF

STATE OF UTAH  
 DEPARTMENT OF NATURAL RESOURCES  
 DIVISION OF OIL, GAS, AND MINING

FORM 10-1 (1984)  
 (Other instructions on reverse side)  
 2

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.

1.  GAS WELL  OTHER

2. NAME OF OPERATOR: SAN JUAN MINERALS

3. ADDRESS OF OPERATOR: RT 1 BOX 52 Blythe CO

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. Also space 17 below.)  
2373 FNL + 94' FEL

5. LEASE DESIGNATION: free

6. IS INDIAN ALLOTTEE OR TRUST?

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME: Goodridge

9. WELL NO.: 81.2

10. FIELD AND POOL, OR WILDCAT: Undesignated

11. SEC., T., R., M., OR B.L.K. AND SURVEY OR AREA: Sec 7 T43S19

12. COUNTY OR PARISH: SAN JUAN CO

13. STATE

14. PERMIT NO.: 43 037 30959 15. ELEVATIONS (Show whether of. st. or. etc.): 4146.90

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
<input type="checkbox"/> WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/> PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/> WATER SHUT-OFF	<input type="checkbox"/>
<input type="checkbox"/> FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/> MULTIPLE COMPLETS	<input type="checkbox"/>	<input type="checkbox"/> FRACTURE TREATMENT	<input type="checkbox"/>
<input type="checkbox"/> SHOOT OR ACIDISE	<input type="checkbox"/>	<input type="checkbox"/> ABANDON*	<input type="checkbox"/>	<input type="checkbox"/> SHOOTING OR ACIDIZING	<input type="checkbox"/>
<input type="checkbox"/> REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/> CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. TYPE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of start of proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and points to this work.)

This well HAS NOT BEEN  
 Drilled - plans ARE TO DRILL  
 AS SOON AS CONTRACTOR  
 RETURNS TO FIELD

**RECEIVED**

FEB 27 1984

DIVISION OF  
 GAS & MINING

18. I hereby certify that the foregoing is true and correct.

APPROVED BY: Joe Job TITLE: Sec DATE: 2/25/84

APPROVED BY: \_\_\_\_\_ TITLE: \_\_\_\_\_ DATE: \_\_\_\_\_

OFFICE OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

April 8, 1985

San Juan Minerals  
Route #1, Box 52J  
Blythe, California 92225

Gentlemen:

Re: Well No. Goodridge 81-2 - Sec. 7, T. 42S., R. 19E.,  
San Juan County, Utah - API #43-037-30959

Our records indicate that you have not filed drilling reports for the months of February 1984 to present on the above referred to well. Our rules and regulations stipulate that these reports be filed by the sixteenth of each month until the well is completed.

Enclosed are forms for your convenience in filing the necessary reports as soon as possible but no later than April 22, 1985.

Thank you for your cooperation in this matter.

Sincerely,

A handwritten signature in cursive script that reads "Pam Kenna".

Pam Kenna  
Well Records Specialist

Enclosure  
cc: Dianne R. Nielson  
Ronald J. Firth  
John R. Baza  
File

0161S/57

# SAN JUAN MINERALS EXPLORATION COMPANY

---

ROUTE 1, BOX 52

BLYTHE, CALIFORNIA 92225

April 10, 1985

Pam Kenna  
Oil, Gas and Mining  
355 W. North Temple  
3 Triad Center  
Suite 350  
Salt Lake City, UT 84180

Re: Well No. Goodridge 81-2; Goodridge 72; Goodridge 81-1


In response to your letter of April 8, requested drilling reports on the above wells for the year of 1984 to present.

On October 18, 1983 we received a letter from Norman C. Stout rescinding the approval to drill on the above wells. I ceased filing reports because we no longer had approval to drill on these well sites.

Am I supposed to continue to file reports on well applications that have been rescinded? If so, what am I supposed to report?

Please let me know what is required and I will comply.

Sincerely,



Jill Johnson

RECEIVED

APR 16 1985

DIVISION OF OIL  
GAS & MINING



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

April 26, 1985

San Juan Minerals Exploration Co.  
Attention: Jill Johnson  
Route 1, Box 52  
Blythe, California 92225

Dear Jill:

Re: Well No: Goodridge 72 - Sec. 8, T. 42S., R. 19E.,  
San Juan County, Utah - API #43-037-30969

Well No.: Goodridge 81-1 - Sec. 8, T. 42S., R. 19E.,  
San Juan County, Utah - API #43-037-30961

Well No.: Goodridge 81-2 - Sec. 7, T. 42S., R. 19E.,  
San Juan County, Utah - API #43-037-30959

Regarding your letter dated April 10, 1985, please find enclosed copies of spud notices and sundry notices for the above listed wells. In checking these well files, I cannot locate letters for these wells indicating the applications were rescinded. The Application to Drill for all three wells were not approved until November and December of 1983 (a copy of each approval letter is enclosed).

If you like an extension on the Application to Drill for the Goodridge 72 of up to one year, please complete the enclosed sundry notice.

Regarding the Goodridge 81-1 and 81-2, please complete a sundry notice on each well indicating the status as either in drilling or operations suspended.

Thank you for your prompt attention to this matter.

Sincerely,

Pam Kenna

Well Records Specialist

Enclosures

cc: Dianne R. Nielson  
Ronald J. Firth  
John R. Baza  
File

0170S/79 & 80



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

May 9, 1985

Ms. Jill Johnson  
San Juan Minerals Exploration Company  
Route 1, Box 52  
Blythe, Ca. 92225

Dear Ms. Johnson:

RE: Wells in Sec.7 and 8, T.42S, R.19E, San Juan County, Utah.

Upon receipt of several Sundry Notices dated May 1, 1985, the subject well files were referred to me for action because it appears that there is still some misunderstanding concerning these wells. To help clear up any problems, I have listed in the attached summary the specific wells, their histories, the documents on file with this office and the information required from you. The intended action to be conducted by the Division is also listed.

Your submitted sundry notices requesting extensions of approval to drill the referenced wells are being returned to you unapproved. It is not my intent to burden you with a lot of additional paperwork; however, I am concerned that when approval to drill is given, operations should commence within a reasonable length of time. I feel that all three of the subject wells were allowed adequate time for commencement of drilling operations and that extensions of approval to drill should not be allowed without proper justification. Therefore, if the information requested in the attached summary is not received, the Division will take action as indicated.

Thank you for your consideration. If you have additional questions concerning this matter, please contact me at this office.

Sincerely,

  
John R. Baza  
Petroleum Engineer

sb  
cc: R.J. Firth  
Well Files  
0090T-83-85

Well No. Goodridge 72, Sec.8, T42S, R.19E:

HISTORY:

Original application to drill was approved in December, 1979. No action was taken to drill well and because of excessive time delay in commencing drilling operations, approval was rescinded in October, 1983. A second application to drill was approved in December, 1983. No other action has been taken with this well.

DOCUMENTS ON FILE:

Since the current approval was given in December of 1983, one sundry notice dated February 24, 1984, has been received stating that "the well is capped."

INFORMATION REQUIRED:

Because the well has not been spudded, a notice should be submitted indicating an approximate date when work will begin.

INTENDED DIVISION ACTION:

Because of excessive time delay in commencing operations, the Division will take action to rescind approval to drill unless this office receives a firm indication from you that activity will commence in the near future. In addition, if approval is rescinded, the Division will consider withholding approvals on future drilling applications until work has begun on the other wells listed in this attachment.

Well No. Goodridge 81-1, Sec.8, T42S, R.19E:

HISTORY:

Application to drill was approved in November, 1983. Notice of spudding was received from you on January 12, 1984. No other action has been taken.

DOCUMENTS ON FILE:

A notice of spudding was received as mentioned above. A sundry notice dated February 25, 1984 is also on file stating that the well has not been drilled.

INFORMATION REQUIRED:

A notice should be submitted verifying whether or not the well has been spudded. The notice should additionally provide a date when operations are expected to resume.

INTENDED DIVISION ACTION:

Depending on the status of well (spudded or not), the Division will take action to either rescind approval to drill or to issue plug and abandonment directives unless this office receives a firm indication from you that activity will commence in the near future.

Page 2  
May 9, 1985

Well No. Goodridge 81-2, Sec.7, T.42S, R.19E:

**HISTORY:**

Application to drill was approved in November, 1983. Notice of spudding was received from you on January 15, 1984. No other action has taken place.

**DOCUMENTS ON FILE:**

Notice of spudding was received as mentioned above. A sundry notice dated February 25, 1984 is also on file indicating that the well has not been drilled.


**INFORMATION REQUIRED:**

Same as Well No. 81-1.

**INTENDED DIVISION ACTION:**

Same as Well No. 81-1.

Goodridge 81-1 LA	2515 FNL, 80 FWL
Goodridge 80.17 LA	442 FNL, 1365 FWL
Goodridge 80.16 LA	159 FNL, 1430 FWL
* Goodridge 72 LA	893 FNL, 655 FWL
Goodridge 71 LA	919 FNL, 294 FWL
* Goodridge 71 P-A	919 FNL, 294 FWL
Goodridge 2 LA	1100 FWL, 840 FNL
Goodridge 1-79 LA	630 FWL, 1706 FNL



SCALE 1:1000

SECTION 8

TOWNSHIP 42S

RANGE 19E

COUNTY San Juan

# SAN JUAN MINERALS EXPLORATION COMPANY

ROUTE 1, BOX 52

BLYTHE, CALIFORNIA 92225

May 14, 1985

RECEIVED

Oil, Gas and Mining  
355 W. North Temple  
3 Triad Center Suite 350  
Salt Lake City, UT 84180

MAY 16 1985

DIVISION OF OIL  
GAS & MINING


Re: Wells in Section 7, 8, T 42 S R 19 E San Juan County, UT

In response to your letter of May 9, 1985 regarding rescission of approval to drill. Neither of the three wells have been drilled at this time.

As indicated in an earlier letter, we thought the approval had already been rescinded. In order to save paper work on both sides, perhaps it is best that approval be rescinded.

I am sorry for the confusion. At this time I can not say when work would start on these wells. If we decide to drill these wells at a later date, I will submit a new application to drill for your approval.

Sincerely,

  
Jill Johnson



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

June 6, 1985

San Juan Minerals Exploration Co.  
Route 1, Box 52  
Blythe, California 92225


Gentlemen:

Re: Well No. Goodridge 81-2 - Sec. 7, T. 42S., R. 19E.,  
San Juan County, Utah - API #43-037-30959

Due to excessive time delay in commencing drilling operations approval to drill the subject well is hereby rescinded, effective one calendar month from the date of this notice. If any operations have been performed on this well location it is imperative that you notify this division immediately.

A new "Application for Permit to Drill" must be filed with this office for approval, prior to future drilling of the subject location.

Sincerely,

  
John R. Baza  
Petroleum Engineer

pk  
cc: Dianne R. Nielson  
Ronald J. Firth  
File

0170S/68